


Map 1 Cooke Rd to Meadowbrook Rd

- floodwater path where water was flowing significantly outside the main brook channel
- new channel temporary new channel created by floodwater
- bank erosion
- flood deposition on road mud, gravel, debris removed by town
- road damage
- municipal sewer system damage
- bridge destroyed
- bridge damaged
- erosion at bridge

- Building affected by flooding:
- total loss destroyed, or damaged to the point of no use in the future
 - major, structural repairable, significant structural damage
 - major, other repairable, damage primarily to building systems (utilities), with structural impact less significant
 - minor generally minor water damage, water in basement




Tropical Storm Irene Damage Whetstone Brook, Brattleboro, Vt.



- Data sources:
- Brattleboro Public Works Department (Gary King), specifically road, bridge, and sewer line damage
 - Brattleboro Planning Services Department (Brian Bannon), specifically building damage
 - Brattleboro Fire Department (Pete Lynch)
 - Windham Regional Commission

Note: data exist for the corridor to the Marlboro town line, but are not shown on this map.



Map 2 Meadowbrook Rd to the Connecticut River